


Note: CR reference conservation rooflight manufactured by The Metal Window Company tel. 01993 830613

Elevations notes:
 All tiled roofs to be repaired and extg tiles relaid.
 All flashings repaired as required.
 Extg cast iron rainwater goods to be repaired.
 Missing gutters to be reinstated with cast iron half round gutters on rise and fall brackets.
 Missing down pipes to be replaced with round cast iron pipes.
 All rainwater goods to be painted light grey to match extg.



- N1 Extg door replaced with timber stable door.
- N2 Extg barn doors replaced
New timber and glass sliding / folding doors within opening
- N3 Form new opening with arched head and fit new timber casement window.
- N4 Fit new timber casement window within existing opening.
- N5 Fit new fixed light casement window within high level opening.
- N6 Reinstated existing opening and fit new timber casement window.
- N7 Repair existing window and reglaze.
- N8 Construct new timber boarded panel behind extg. opening
- N9 Diamond pattern in brickwork infilled with cast glass set back 115 from face.



PROJECT
MAYFIELD HALL

CLIENT
MR & MRS BRETT

SUBJECT
ST MICHAEL'S
QUEEN STREET
DERBY DE1 3SU
TEL: 01332 365777
FAX: 01332 290314
info@lathamarchitects.co.uk

Conversion of existing outbuildings to holiday lets:
The Coach House
proposed plans and elevations

ARCHITECTURE
CONSERVATION
PLANNING
LANDSCAPE
INTERIORS

DRAWN Greenhatch /GR **CHECKED** SH

NUMBER 2146B / P / 24
Revision
PLANNING APPLICATION

SCALE 1:100 + 1:200 **DATE** NOV 2005
@ A3

creative reuse of land and buildings

© This drawing and the building works depicted are the copyright of the architect and may not be reproduced except with written consent. Written dimensions should be taken in preference to scaled dimensions.